# Oil Field Environmental Incident Summary

Responsible Party: DENBURY ONSHORE, LLC
Well Operator: DENBURY ONSHORE, LLC
Well Name: CEDAR CREEK UNIT 24X-07C-73

Field Name: CEDAR CREEK Well File #: 14192

Date Incident:2/6/2016Time Incident:15:00Facility ID Number:County:BOWMANTwp:130Rng:106Sec:7Qtr:

Location Description: On location

Submitted By: Josh Cuppy Received By:

Contact Person: Josh Cuppy

5320 LEGACY DR

PLANO, TX 75024-3127

General Land Use: Pasture Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 30 Barrels 30 Barrels 30 barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 2/16/2016 Clean Up Concluded: 2/11/2016

Risk Evaluation:

None

Areal Extent:

leak filled the cellar and the inside of the building. Pooled around building.

# Potential Environmental Impacts:

None

# Action Taken or Planned:

Shut in. Recovered standing fluid. Impacted area will be washed. Repairs will be made.

Wastes Disposal Location: Facility.

Agencies Involved: BLM

# **Updates**

Date: 2/8/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

According to the report, 30 barrels of brine were released and contained within the facility diking. NDIC retains oversight.